



# FIRMWARE 2.4.16 RELEASE NOTES

---

February 5, 2021

## **Issue Fix - Compatibility With New BeiDou Corrections When Connected to Skylark OSR**

In January 2021, support for BeiDou was added to Skylark™. BeiDou corrections are now available in the United States and will be available in Europe—and other areas—in the near future. These new corrections are not compatible with Piksi® Multi / Duro® / Duro Inertial Firmware v2.4.15 and they will cause the unit to restart when receiving BeiDou corrections.

All current users of Skylark OSR in the United States with a Piksi Multi, Duro, or Duro Inertial on Firmware v2.4.15 are impacted. All users of Skylark OSR outside of the United States with a Piksi Multi, Duro or Duro Inertial on firmware v2.4.15 will be impacted once BeiDou support is deployed in their area.

The Firmware v2.4.16 update solves this issue and allows Piksi Multi, Duro and Duro Inertial to operate seamlessly with these new BeiDou corrections.

In the Getting Started Guide, refer to Section 7 entitled [Upgrading Firmware](#) for detailed instructions on how to upgrade your device. [Firmware release binaries](#) and product support documents are available at [support.swiftnav.com](http://support.swiftnav.com).